
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/21/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S02AA1018MH	Test ID: <u>D1032-027017</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S02AA1028MH
0			Water Level	
0			Start of Survey	
169.5	02		Tap Factory	From 4812 Gwynn Oak
169.5			Dye Test Visible	@ TF - downspout
195.1000061			General Observation	NO MORE CLOSE TAPS
195.1000061			End of Survey	DYE TEST COMPLETED
195.1000061			Manhole	S02AA1018MH